

Inspection Report

Sample Report

Property Address: 456 Main St. Irvine CA



Guaranteed Property and Mold Inspections.

Joseph Gutierrez 2372 Morse Ave. Suite 257 Irvine, CA 92614 949.230.6800

456 Main St. Page 2 of 200

Table of Contents

Cover Page	<u>1</u>
Table of Contents	
Intro Page	4
1 Structural Components	5
2 Exterior	6
3 Electrical System	28
4 Roofing / Chimneys / Roof Structure and Attic .	43
5 Plumbing System	47
6 Garage	49
7 Laundry	52
8 Water Heater	<u>53</u>
9 Kitchen Components and Appliances	<u>57</u>
10 Heating / Central Air Conditioning	
11 Interior	74
12 Bathroom and Components	
13 Indoor Air Quality	
14 Energy Conservation	
General Summary	
Attachments	

456 Main St. Page 3 of 200

Date: 11/21/2019	Time: 10:00 AM	Report ID: MainStlrvine
Property: 456 Main St. Irvine CA	Customer: Sample Report	Real Estate Professional:

Comment Key or Definitions

The following definitions of comment descriptions represent this inspection report. All comments by the inspector should be considered before purchasing this home. Any recommendations by the inspector to repair or replace suggests a second opinion or further inspection by a qualified contractor. All costs associated with further inspection fees and repair or replacement of item, component or unit should be considered before you purchase the property.

<u>Inspected (IN)</u> = I visually observed the item, component or unit and if no other comments were made then it appeared to be functioning as intended allowing for normal wear and tear.

Not Inspected (NI)= I did not inspect this item, component or unit and made no representations of whether or not it was functioning as intended and will state a reason for not inspecting.

Not Present (NP) = This item, component or unit is not in this home or building.

Evaluate/Service (ES) = This item, component or unit needs further evaluation or service due to: wear, age, lack of maintenance, marginal functioning or requires further explanation.

Repair or Replace (RR) = The item, component or unit is not functioning as intended, or needs further inspection by a qualified contractor. Items, components or units that can be repaired to satisfactory condition may not need replacement.

Approximate age of building: Temperature: Weather:
Over 10 Years Over 65 Clear

Ground/Soil surface condition: Rain in last 3 days: Radon Test:
Damp No No

Water Test:
No

456 Main St. Page 4 of 200

1. Structural Components

The Home Inspector shall observe structural components including foundations, floors, walls, columns or piers, ceilings and roof. The home inspector shall describe the type of Foundation, floor structure, wall structure, columns or piers, ceiling structure, roof structure. The home inspector shall: Enter under floor crawl spaces, basements, and attic spaces except when access is obstructed, when entry could damage the property, or when dangerous or adverse situations are suspected; Report the methods used to observe under floor crawl spaces and attics; and Report signs of abnormal or harmful water penetration into the building or signs of abnormal or harmful condensation on building components. The home inspector is not required to: Enter any area or perform any procedure that may damage the property or its components or be dangerous to or adversely effect the health of the home inspector or other persons.

Styles & Materials

Foundation:Floor Structure:Wall Structure:Poured concreteSlabWood

Items

1.0 Foundations

Comments: Inspected

1.1 Walls (Structural)

Comments: Inspected

1.2 Floors (Structural)

Comments: Inspected

1.3 Ceilings (Structural)

Comments: Inspected

1.4 Seismic System(s)

Comments: Not Inspected

Not fully visible, Houses built in California since 1942 have required seismic bolt installation.

The structure of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

456 Main St. Page 5 of 200

2. Exterior

The home inspector shall observe: Wall cladding, flashings, and trim; Entryway doors and a representative number of windows; Garage door operators; Decks, balconies, stoops, steps, areaways, porches and applicable railings; Eaves, soffits, and fascias; and Vegetation, grading, drainage, driveways, patios, walkways, and retaining walls with respect to their effect on the condition of the building. The home inspector shall: Describe wall cladding materials; Operate all entryway doors and a representative number of windows; Operate garage doors manually or by using permanently installed controls for any garage door operator; Report whether or not any garage door operator will automatically reverse or stop when meeting reasonable resistance during closing; and Probe exterior wood components where deterioration is suspected. The home inspector is not required to observe: Storm windows, storm doors, screening, shutters, awnings, and similar seasonal accessories; Fences; Presence of safety glazing in doors and windows; Garage door operator remote control transmitters; Geological conditions; Soil conditions; Recreational facilities (including spas, saunas, steam baths, swimming pools, tennis courts, playground equipment, and other exercise, entertainment, or athletic facilities); Detached buildings or structures; or Presence or condition of buried fuel storage tanks. The home inspector is not required to: Move personal items, panels, furniture, equipment, plant life, soil, snow, ice or debris that obstructs access or visibility.

Styles & Materials

Siding Style: Siding Material: Exterior Entry Doors:

Cement stucco Stucco Wood

Appurtenance: Driveway:
Patio Concrete

Items

2.0 Wall Cladding, Flashing and Trim

Comments: Evaluation/Service

456 Main St. Page 6 of 200

(1) Signs of stucco repairs observed at the left side of the structure; we recommend further inquiry of the seller.



2.0 Item 1(Picture) Left side of the structure.

456 Main St. Page 7 of 200



2.0 Item 2(Picture) Left side of the structure.

456 Main St. Page 8 of 200

(2) Poor weep screed clearance (2" above paving; 4" above soil); this condition results in corrosion, and unwanted moisture intrusion into the wall and interior that may not be readily visible.



2.0 Item 3(Picture) Left side of the structure (planter)

(3) Stucco is susceptible to cracking. Cracks to not imply that the function has been degraded. Only cracks larger than 3/32" and excessive indicate a problem. We recommend however, that all cracks by sealed by a stucco professional.

2.1 Doors (Exterior)

Comments: Repair or Replace


456 Main St. Page 9 of 200

The front door handle appears to have been replaced; cracks exist around the handle; we recommend repairs.



2.1 Item 1(Picture) Front door.

456 Main St. Page 10 of 200



2.1 Item 2(Picture) Front door.

456 Main St. Page 11 of 200



2.1 Item 3(Picture) Front door.

2.2 Windows

Comments: Evaluation/Service


456 Main St. Page 12 of 200

(1) The wood trim at the exterior window front of the structure are moisture damaged; we recommend further evaluation and repairs by a termite professional.



2.2 Item 1(Picture) Front of the structure.

456 Main St. Page 13 of 200



2.2 Item 2(Picture) Front of the structure.



2.2 Item 3(Picture) Front of the structure.

456 Main St. Page 14 of 200

(2) Caulking deterioration at the front of the structure, we recommend servicing.



2.2 Item 4(Picture) Front of the structure.

456 Main St. Page 15 of 200



2.2 Item 5(Picture) Front of the structure.

2.3 Decks, Balconies, Areaways, Porches, and Applicable Railings

Comments: Inspected

2.4 Eaves, Soffits, Fascias, Beam Ends and Rafters

Comments: Evaluation/Service

456 Main St. Page 16 of 200

Moisture damage; we recommend further evaluation by a termite professional, to determine the extent of moisture damage to the wood structure.




2.4 Item 1(Picture) Front of the structure.

456 Main St. Page 17 of 200



2.4 Item 2(Picture) Front of the structure.



2.4 Item 3(Picture) Right side of the structure.

456 Main St. Page 18 of 200



2.4 Item 4(Picture) Right side of the structure.

2.5 Plumbing Water Faucets (hose bibs)

Comments: Inspected

2.6 Outlets and Wiring (Exterior)

Comments: Inspected

2.7 Grade and Slope

Comments: Inspected

2.8 Grade Clearance to Walls

Comments: Inspected

2.9 Retaining Walls

Comments: Not Inspected

Present and beyond the scope of this inspection; walls with cracks or leaning should be evaluation by a structural engineer.

2.10 Driveway

Comments: Inspected

2.11 Walkways


Comments: Inspected

2.12 Sprinklers

Comments: Evaluation/Service

456 Main St. Page 19 of 200

Sprinkler system leaking at the right side of the structure; we recommend corrections by a plumber.



2.12 Item 1(Picture) Right side of the structure.

2.13 Door Bell

Comments: Inspected

2.14 Insects

Comments: Inspected

2.15 Trees and Plants

Comments: Evaluation/Service

456 Main St. Page 20 of 200

(1) Neighbor tree over roof area, we recommend trimming to protect the roof coverings.



2.15 Item 1(Picture) Roof.

456 Main St. Page 21 of 200

(2) Touching the structure, we recommend trimming.



2.15 Item 2(Picture) Right side of the structure.

2.16 Grounds Lighting

Comments: Inspected

2.17 Fences, Walls and Gates

Comments: Evaluation/Service


456 Main St. Page 22 of 200

It appears that sprinkler water is spraying the perimeter fence; this can allow deterioration of the wall and stucco damage; we recommend switching to a drip system and repairs by a stucco professional.



2.17 Item 1(Picture) Right side of the structure.

456 Main St. Page 23 of 200



2.17 Item 2(Picture) Rear of the structure.



2.17 Item 3(Picture) Rear of the structure.

456 Main St. Page 24 of 200



2.17 Item 4(Picture) Rear of the structure.

456 Main St. Page 25 of 200



2.17 Item 5(Picture) Rear of the structure.

2.18 Steps and Railings

Comments: Inspected

2.19 Patio Cover

Comments: Inspected

456 Main St. Page 26 of 200



2.19 Item 1(Picture) Patio cover.

2.20 Patio

Comments: Inspected

2.21 Drainage

Comments: Inspected

2.22 Guardrails

Comments: Inspected

The exterior of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

456 Main St. Page 27 of 200

3. Electrical System

The home inspector shall observe: Service entrance conductors; Service equipment, grounding equipment, main over current device, and main and distribution panels; Amperage and voltage ratings of the service; Branch circuit conductors, their over current devices, and the compatibility of their ampacities and voltages; The operation of a representative number of installed ceiling fans, lighting fixtures, switches and receptacles located inside the house, garage, and on the dwelling's exterior walls; The polarity and grounding of all receptacles within six feet of interior plumbing fixtures, and all receptacles in the garage or carport, and on the exterior of inspected structures; The operation of ground fault circuit interrupters; and Smoke detectors. The home inspector shall describe: Service amperage and voltage; Service entry conductor materials; Service type as being overhead or underground; and Location of main and distribution panels. The home inspector shall report any observed aluminum branch circuit wiring. The home inspector shall report on presence or absence of smoke detectors, and operate their test function, if accessible, except when detectors are part of a central system. The home inspector is not required to: Insert any tool, probe, or testing device inside the panels; Test or operate any over current device except ground fault circuit interrupters; Dismantle any electrical device or control other than to remove the covers of the main and auxiliary distribution panels; or Observe: Low voltage systems; Security system devices, heat detectors, or carbon monoxide detectors; Telephone, security, cable TV, intercoms, or other ancillary wiring that is not a part of the primary electrical distribution system; or Built-in vacuum equipment.

Styles & Materials

Electrical Service Conductors: Panel capacity: Panel Type:

Below ground 200 AMP Circuit breakers

Branch wire 15 and 20 AMP: Wiring Methods:

Copper Conduit

Items

3.0 Service Entrance Conductors

Comments: Inspected

3.1 Panel Access

Comments: Inspected

3.2 Service Main and Distribution Panels


Comments: Inspected

456 Main St. Page 28 of 200



3.2 Item 1(Picture) Service panel.

456 Main St. Page 29 of 200



3.2 Item 2(Picture) Service panel.

3.3 Location of Main and Distribution Panels

Comments: Inspected
3.4 Grounding and Bonding
Comments: Inspected
3.5 Main Panel Disconnect


Comments: Inspected

3.6 Branch Circuit Conductors, Overcurrent Devices and Compatability of their Amperage and Voltage

Comments: Evaluation/Service


456 Main St. Page 30 of 200

Loose breakers we recommend evaluation by a licensed electrician for enhanced safety.




3.6 Item 1(Picture) Service panel.

456 Main St. Page 31 of 200



3.6 Item 2(Picture) Service panel.



3.6 Item 3(Picture) Service panel.

3.7 Panel Labels

Comments: Inspected

3.8 Connected Devices and Fixtures (Observed from a representative number operation of ceiling fans, lighting fixtures, switches and receptacles located inside the house, garage, and on the dwelling's exterior walls)

Comments: Inspected

456 Main St. Page 32 of 200

3.9 Grounding (and or GFCI) of Receptacles within 6 feet of interior plumbing fixtures, and all receptacles in garage, carport and exterior walls

Comments: Repair or Replace

We recommend that all outlets within 6' of wet areas be upgraded to GFCI for enhanced safety.



3.9 Item 1(Picture) Kitchen island.

456 Main St. Page 33 of 200




3.9 Item 2(Picture) Kitchen island.

456 Main St. Page 34 of 200




3.9 Item 3(Picture) Kitchen island.

456 Main St. Page 35 of 200



3.9 Item 4(Picture) Laundry room.

456 Main St. Page 36 of 200



3.9 Item 5(Picture) Laundry room.

456 Main St. Page 37 of 200



3.9 Item 6(Picture) Lower hallway bathroom.

456 Main St. Page 38 of 200




3.9 Item 7(Picture) Master bathroom.

456 Main St. Page 39 of 200



3.9 Item 8(Picture) Master bathroom.

456 Main St. Page 40 of 200



3.9 Item 9(Picture) Master bathroom.

3.10 Operation of GFCI (Ground Fault Circuit Interrupters)

Comments: Inspected

3.11 Smoke Detectors

Comments: Inspected

The seller is required to provide written certification that smoke detector are in compliance. NOTE that newer photoelectric alarms are considered more reliable than older ionization types; Kiddie has a dual alarm for about \$18, we recommend you upgrade for enhanced safety.e

3.12 Carbon Monoxide Detectors

Comments: Inspected

Required at each level of the home that has a gas appliance or attached garage; placed outside and near of sleeping areas; at any height. Carbon monoxide is the leading cause of poisoning death in the U.S.

456 Main St. Page 41 of 200

The electrical system of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Outlets were not removed and the inspection was only visual. Any outlet not accessible (behind the refrigerator for example) was not inspected or accessible. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

456 Main St. Page 42 of 200

4. Roofing / Chimneys / Roof Structure and Attic

The home inspector shall observe: Roof covering; Roof drainage systems; Flashings; Skylights, chimneys, and roof penetrations; and Signs of leaks or abnormal condensation on building components. The home inspector shall: Describe the type of roof covering materials; and Report the methods used to observe the roofing. The home inspector is not required to: Walk on the roofing; or Observe attached accessories including but not limited to solar systems, antennae, and lightning arrestors.

Styles & Materials

Viewed roof covering from:Roof-Type:Roof Covering:GroundGableConcrete

Ladder

Chimney (exterior): Roof Ventilation: Method used to observe attic:

EIFS/Stucco Gable vents Walked

Roof Structure: Ceiling Structure: Attic info:

Lateral bracing 2X4 Attic access

Attic Insulation: Fiberglass

Items

4.0 Roof Coverings

Comments: Inspected

(1) Roofs are evaluated by ladder, binocular, attic observation, and eaves. When possible we will also use a drone for higher level roofs. We do not walk roofs due to requirements of our insurance carrier, and to avoid damage to the roof material.

(2) Life expectancy: 30-50 years.

4.1 Flashings

Comments: Inspected

4.2 Skylights and Roof Penetrations

Comments: Inspected

4.3 Roof Ventilation

Comments: Inspected

4.4 Roof Drainage Systems (gutters and downspouts)

Comments: Evaluation/Service

456 Main St. Page 43 of 200

The downspout at the front of the structure is not mounted to the wall; we recommend repairs.



4.4 Item 1(Picture) Front of the structure.

456 Main St. Page 44 of 200



4.4 Item 2(Picture) Front of the structure.

4.5 Chimney(s)

Comments: Inspected

We recommend a level 2 safety inspection by a certified chimney sweep for all chimneys.

4.6 Roof Structure and Attic

Comments: Inspected

4.7 Ventilation Fans and Thermostatic Controls (Attic)

Comments: Inspected
4.8 Insulation in Attic
Comments: Inspected
4.9 Insects/Rodents Attic

Comments: Inspected

456 Main St. Page 45 of 200

4.10 Visible Electric Wiring in Attic

Comments: Evaluation/Service

Exposed splices, we recommend a complete evaluation of the electrical system in the attic since this is an indication that work was not completed by a licensed electrician; this is a safety hazard.



4.10 Item 1(Picture) Attic.

4.11 Access Cover Attic

Comments: Inspected

The roof of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Roof coverings and skylights can appear to be leak proof during inspection and weather conditions. Our inspection makes an attempt to find a leak but sometimes cannot. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

456 Main St. Page 46 of 200

5. Plumbing System

The home inspector shall observe: Interior water supply and distribution system, including: piping materials, supports, and insulation; fixtures and faucets; functional flow; leaks; and cross connections; Interior drain, waste, and vent system, including: traps; drain, waste, and vent piping; piping supports and pipe insulation; leaks; and functional drainage; Hot water systems including: water heating equipment; normal operating controls; automatic safety controls; and chimneys, flues, and vents; Fuel storage and distribution systems including: interior fuel storage equipment, supply piping, venting, and supports; leaks; and Sump pumps. The home inspector shall describe: Water supply and distribution piping materials; Drain, waste, and vent piping materials; Water heating equipment; and Location of main water supply shutoff device. The home inspector shall operate all plumbing fixtures, including their faucets and all exterior faucets attached to the house, except where the flow end of the faucet is connected to an appliance. The home inspector is not required to: State the effectiveness of anti-siphon devices; Determine whether water supply and waste disposal systems are public or private; Operate automatic safety controls; Operate any valve except water closet flush valves, fixture faucets, and hose faucets; Observe: Water conditioning systems; Fire and lawn sprinkler systems; On-site water supply quantity and quality; On-site waste disposal systems; Foundation irrigation systems; Spas, except as to functional flow and functional drainage; Swimming pools; Solar water heating equipment; or Observe the system for proper sizing, design, or use of proper materials.

Styles & Materials

Water Source: Water Filters: Plumbing Water Supply (into home):

Public (We do not inspect filtration systems) Copper

Plumbing Water Distribution (inside home): Washer Drain Size: Plumbing Waste Line:

PEX 2" Diameter ABS

Water Heater Power Source: Water Heater Capacity: Waste Water System:

Gas (quick recovery) 75 Gallon Public

Fuel Source: Natural Gas

Items

5.0 Plumbing Drain, Waste and Vent Systems

Comments: Inspected

Some ABS pipes installed between 1984 and 1990 cracked at pipe joints due to improper glue.

5.1 Plumbing Water Supply and Distribution Systems

Comments: Inspected

5.2 Main Water Shut-off Device

Comments: Inspected

5.3 Water Pressure

Comments: Inspected

5.4 Functional Flow

Comments: Inspected

5.5 Fuels Storage and Distribution Systems

Comments: Inspected

5.6 Main Fuel Shut-off

Comments: Repair or Replace

456 Main St. Page 47 of 200

Gas meter lacks seismic shut off device, we recommend installation for enhanced safety.



5.6 Item 1(Picture) Gas meter.

5.7 Gas Sediment Trap(s)

Comments: Inspected

5.8 Sump Pump

Comments: Not Present

5.9 Wet Bar

Comments: Not Present

The plumbing in the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Washing machine drain line for example cannot be checked for leaks or the ability to handle the volume during drain cycle. Older homes with galvanized supply lines or cast iron drain lines can be obstructed and barely working during an inspection but then fails under heavy use. If the water is turned off or not used for periods of time (like a vacant home waiting for closing) rust or deposits within the pipes can further clog the piping system. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

456 Main St. Page 48 of 200

6. Garage

All garage doors should be equipped with an optical safety reverse. ATTACHED GARAGES should not have stored flammable materials, door entering sleeping rooms, and a self closing firedoor. Occupant belongings limit inspection observations.

Styles & Materials

Garage Door Type:

Garage Door Material:

Two automatic

Fiberglass

Items

6.0 Garage Ceiling

Comments: Inspected

6.1 Garage Walls (Including Firewall Separation)

Comments: Inspected

6.2 Foundation

Comments: Inspected

6.3 Garage Floor

Comments: Inspected

6.4 Garage Vehicle Door (s)

Comments: Inspected

6.5 Garage Door Controls and Auto Reverse

Comments: Repair or Replace

456 Main St. Page 49 of 200

Optical sensors are more than 6" above the ground, recommend corrections for child and pet safety.




6.5 Item 1(Picture) Garage.

6.6 Occupant Door from Garage to inside home

Comments: Repair or Replace

456 Main St. Page 50 of 200

The occupant door from inside garage to inside the home is not a fire rated door. This means that should a fire occur in garage, the occupant door does not afford protection until fireman arrive. This door should be replaced with a fire rated door.



6.6 Item 1(Picture) Garage door.

6.7 Exterior Door

Comments: Inspected

6.8 Electrical

Comments: Inspected

6.9 Ventilation

Comments: Inspected

456 Main St. Page 51 of 200

7. Laundry

Laundry appliances, drainage, 240 outlets and dryer venting are beyond the scope of this inspection. Washer valves are not operated. We recommend gas dryers for energy savings. Washers should be equiped with non-burst hoses.

Items

7.0 Walls

Comments: Inspected

7.1 Ceiling

Comments: Inspected

7.2 Floor

Comments: Inspected7.3 Dryer Moisture VentingComments: Inspected

A dryer vent system is inspected, but is not readily visible for a complete inspection as to its efficiency. Periodic inspection and cleaning of the dryer vent system ins strongly recommended. Lint build up in the dryer and vent system poses a fire and safety risk; and is one of the leading causes of residential appliance fires.

7.4 Room Ventilation

Comments: Inspected

7.5 Electrical

Comments: Inspected

7.6 Gas Supply

Comments: Inspected

7.7 Washer Valves

Comments: Inspected

7.8 Washer Drain

Comments: Inspected

7.9 Sink

Comments: Inspected

7.10 Door

Comments: Inspected

456 Main St. Page 52 of 200

8. Water Heater

Water heater thermostats are not tested due to owner presets; we recommend keeping the setting above 120 degrees to prevent legionaries bacteria. Units should be protected from damage and above 18" from the ground unless FVIR. For seismic bracing requirements visit: www.seismic.ca.gov/HOG/waterheaterbracing_08-11-04.pdf.

Styles & Materials


New:

Gas

Items

8.0 Condition

Comments: Inspected



8.0 Item 1(Picture) Water heater.

456 Main St. Page 53 of 200

8.1 Energy Source

Comments: Inspected

8.2 Plumbing Connections

Comments: Repair or Replace

Hot and cold water lines are missing R-4 insulation, we recommend installation for energy savings.



8.2 Item 1(Picture) Water heater.

8.3 Vent/Flue

Comments: Inspected 8.4 Pressure Relief Valve

Comments: Inspected

8.5 Overflow Pan

Comments: Inspected

8.6 Seismic Strapping

Comments: Repair or Replace

456 Main St. Page 54 of 200

52+ size water heater requires a third seismic strap at mid-line, we recommend installation to meet CA seismic guidelines.



8.6 Item 1(Picture) Water heater.

8.7 Firewall/Platform

Comments: Evaluation/Service

456 Main St. Page 55 of 200

The water heater appears to be slightly leaning; we recommend further evaluation by a licensed plumber.



8.7 Item 1(Picture) Water heater.

8.8 Recirculation Pump

Comments: Not Present

8.9 Expansion Tank

Comments: Not Present

456 Main St. Page 56 of 200

9. Kitchen Components and Appliances

The home inspector shall observe and operate the basic functions of the following kitchen appliances: Permanently installed dishwasher, through its normal cycle; Range, cook top, and permanently installed oven; Trash compactor; Garbage disposal; Ventilation equipment or range hood; and Permanently installed microwave oven. The home inspector is not required to observe: Clocks, timers, self-cleaning oven function, or thermostats for calibration or automatic operation; Non built-in appliances; or Refrigeration units. The home inspector is not required to operate: Appliances in use; or Any appliance that is shut down or otherwise inoperable.

Cabinetry:

Styles & Materials

Exhaust/Range hood:

VENTED Wood

Items

9.0 Ceiling

Comments: Inspected

9.1 Walls

Comments: Inspected

9.2 Floor

Comments: Inspected
9.3 Pantry/Closet Doors
Comments: Inspected

9.4 Windows

Comments: Inspected

9.5 Representative number of Cabinets

Comments: Inspected

9.6 Counters

Comments: Inspected

9.7 Plumbing Drain and Vent Systems

Comments: Inspected

9.8 Plumbing Supply Faucets, Fixtures and Sink

Comments: Inspected

Effective 2017, homes built before 1994 require water conserving plumbing fixtures exceeding: interior faucets 2.2

gallons per minute. REFER TO YOUR TRANSFER DISCLOSURE STATEMENT.

9.9 Outlets Wall Switches and Fixtures

Comments: Inspected

9.10 Lighting

Comments: Inspected

9.11 Dishwasher


Comments: Inspected

9.12 Air Gap

Comments: Repair or Replace

456 Main St. Page 57 of 200

Not installed, this can result in waste water mixing into the clean cycle; note that a few models have an internal air gap (which is not common); recommend installation for water quality safety.



9.12 Item 1(Picture) Air gap.

9.13 Ranges/Ovens/Cooktops

Comments: Inspected

9.14 Range Hood

Comments: Repair or Replace

456 Main St. Page 58 of 200

(1) Disconnected at the exhaust, we recommend correction by securing with 3 metal sheet screws at each end and sealing with aluminum tape.



9.14 Item 1(Picture) Range exhaust.



9.14 Item 2(Picture) Range exhaust.

456 Main St. Page 59 of 200

(2) The left side heating bulb did not respond to test; we recommend replacement.



9.14 Item 3(Picture) Range hood.

9.15 Trash Compactor

Comments: Not Present

9.16 Food Waste Disposer

Comments: Inspected

9.17 Microwave Cooking Equipment

Comments: Inspected

The built-in appliances of the home were inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

456 Main St. Page 60 of 200

10. Heating / Central Air Conditioning

The home inspector shall observe permanently installed heating and cooling systems including: Heating equipment; Cooling Equipment that is central to home; Normal operating controls; Automatic safety controls; Chimneys, flues, and vents, where readily visible; Solid fuel heating devices; Heat distribution systems including fans, pumps, ducts and piping, with supports, insulation, air filters, registers, radiators, fan coil units, convectors; and the presence of an installed heat source in each room. The home inspector shall describe: Energy source; and Heating equipment and distribution type. The home inspector shall operate the systems using normal operating controls. The home inspector shall open readily openable access panels provided by the manufacturer or installer for routine homeowner maintenance. The home inspector is not required to: Operate heating systems when weather conditions or other circumstances may cause equipment damage; Operate automatic safety controls; Ignite or extinguish solid fuel fires; or Observe: The interior of flues; Fireplace insert flue connections; Humidifiers; Electronic air filters; or The uniformity or adequacy of heat supply to the various rooms.

Styles & Materials

Heat Type: Energy Source: Number of Heat Systems (excluding wood):

Forced Air Gas Three

Ductwork:Filter Type:Types of Fireplaces:InsulatedDisposableGas/LP Log starter

Operable Fireplaces: Cooling Equipment Type: Cooling Equipment Energy Source:

One Central Air conditioner unit Electricity

Number of AC Only Units:

Two

Items

10.0 Heating Equipment

Comments: Inspected

10.1 Fuel Supply

Comments: Inspected

10.2 Heater Exhaust Vent
Comments: Inspected

10.3 Plenums

Comments: Inspected

10.4 Automatic Safety Controls

Comments: Inspected

10.5 Heater Burners and Elements

Comments: Inspected

10.6 Enclosure

Comments: Evaluation/Service

456 Main St. Page 61 of 200

Possible rodent droppings observed at the HVAC enclosure; we recommend further evaluation and cleanup by a integrated pest control specialist.



10.6 Item 1(Picture) HVAC enclosure.

456 Main St. Page 62 of 200



10.6 Item 2(Picture) HVAC enclosure.

10.7 Normal Operating Controls

Comments: Inspected

10.8 Distribution Systems (including visible fans, pumps, ducts and piping).

Comments: Evaluation/Service

456 Main St. Page 63 of 200

Aging ducts, we recommend leak testing, and budgeting for replacement. NOTE THAT DUCTS SHOULD NOT BE CLEANED.




10.8 Item 1(Picture) HVAC ducting.

456 Main St. Page 64 of 200



10.8 Item 2(Picture) HVAC ducting.

456 Main St. Page 65 of 200



10.8 Item 3(Picture) HVAC ducting.

10.9 Air Return Chamber

Comments: Repair or Replace

456 Main St. Page 66 of 200

Lacks drywall enclosure, recommend installation to eliminate using air from inner walls of the structure.



10.9 Item 1(Picture) Air return chamber.



10.9 Item 2(Picture) Air return chamber.

10.10 HVAC Filter

Comments: Repair or Replace

456 Main St. Page 67 of 200

(1) Missing at the air return; we recommend replacement with an allergy rated disposable filter.



10.10 Item 1(Picture) Lower hallway.

(2) Poorly sized at the master bedroom, we recommend replacement with an allergy rated disposable filter.



10.10 Item 2(Picture) Master bedroom.

10.11 Presence of installed heat source in each room

Comments: Inspected

10.12 Cooling and Air Handler Equipment

Comments: Inspected

456 Main St. Page 68 of 200

(1)



10.12 Item 1(Picture) HVAC.

456 Main St. Page 69 of 200

(2) The HVAC system located in the attic appeared to be mounted improperly; the system was resting on wood piers; we recommend correction by an HVAC contractor.



10.12 Item 2(Picture) HVAC.



10.12 Item 3(Picture) HVAC.

10.13 AC Condensation Lines

Comments: Evaluation/Service

(1) Not fully visible, leak testing is beyond the scope.

456 Main St. Page 70 of 200

(2) The condensation drip line that terminates to the exterior appears to impact the side wall when draining; we recommend extending the drip line to ensure moisture does not come into contact with the cladding wall.



10.13 Item 1(Picture) Rear of the structure.

(3) A secondary drain line or auto disconnect device was not installed; these should be installed if blockage in the primary line could cause damage to the structure.



10.13 Item 2(Picture) HVAC.

10.14 AC Refrigerant Lines Comments: Not Inspected

456 Main St. Page 71 of 200

Not fully visible, leak testing is beyond the scope.

10.15 AC Condenser

Comments: Inspected

10.16 AC Electrical

Comments: Inspected


10.17 AC Temperature Difference

Comments: Inspected

10.18 Solid Fuel heating Devices (Fireplaces, Woodstove)

Comments: Inspected

Gas appliance requires a clip at the damper to prevent full closure.



10.18 Item 1(Picture) Fireplace.

10.19 Fireplace Damper

Comments: Inspected

10.20 Fireplace Clearance from Combustibles

Comments: Inspected

10.21 Fireplace High Heat Caulk

Comments: Inspected


10.22 Fireplace Glass Door/Screen

Comments: Not Present

456 Main St. Page 72 of 200

Missing screen, we recommend installation for enhanced safety.

Missing glass doors, we recommend installation for enhanced safety and energy conservation.



10.22 Item 1(Picture) Fireplace.

10.23 Fireplace Hearth

Comments: Inspected

The heating and cooling system of this home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. The inspection is not meant to be technically exhaustive. The inspection does not involve removal and inspection behind service door or dismantling that would otherwise reveal something only a licensed heat contractor would discover. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

456 Main St. Page 73 of 200

11. Interior

The home inspector shall observe: Walls, ceiling, and floors; Steps, stairways, balconies, and railings; Counters and a representative number of installed cabinets; and A representative number of doors and windows. The home inspector shall: Operate a representative number of windows and interior doors; and Report signs of abnormal or harmful water penetration into the building or signs of abnormal or harmful condensation on building components. The home inspector is not required to observe: Paint, wallpaper, and other finish treatments on the interior walls, ceilings, and floors; Carpeting; or Draperies, blinds, or other window treatments.

Styles & Materials

Ceiling Materials: Wall Material: Floor Covering(s):

Drywall Drywall Wood

Interior Doors: Window Types:
Wood Dual-pane

Items

11.0 Ceilings

Comments: Evaluation/Service

Signs of repairs noticed at the formal living room ceiling and kitchen ceiling; we recommend further inquiry of the seller.



11.0 Item 1(Picture) Formal living room.

456 Main St. Page 74 of 200



11.0 Item 2(Picture) Formal living room.



11.0 Item 3(Picture) Formal living room.

456 Main St. Page 75 of 200



11.0 Item 4(Picture) Kitchen ceiling.

11.1 Walls

Comments: Evaluation/Service

456 Main St. Page 76 of 200

(1) Signs of warping at the master bedroom wall beneath the windows; this can be due to moisture intrusion from the exterior; we recommend further evaluation by a licensed contractor.



11.1 Item 1(Picture) Master bedroom.

456 Main St. Page 77 of 200



11.1 Item 2(Picture) Master bedroom.

456 Main St. Page 78 of 200

(2) There was damaged observed at the master bedroom closet lower wall; we recommend repairs.



11.1 Item 3(Picture) Master bedroom.

11.2 Floors

Comments: Evaluation/Service

(1) Floor noise at upper level master bedroom closet, this is not atypical for older homes, however it can be an indication of poor installation practices and defects, we recommend further evaluation. These conditions can often be improved by the application of additional screws in the floor boards at the joists.




11.2 Item 1(Picture) Master bedroom closet.

456 Main St. Page 79 of 200

(2) Lifted flooring observed at the upper hallway; we recommend corrections by a licensed contractor.



11.2 Item 2(Picture) Upper hallway flooring.



11.2 Item 3(Picture) Upper hallway flooring.

11.3 Steps, Stairways, and Railings

Comments: Inspected

Stairway accidents are the number one cause of injuries in homes. We recommend that you maintain non-slip surfaces, step integrity, handrails, guardrails and lighting.

456 Main St. Page 80 of 200

11.4 Doors (Representative number)


Comments: Evaluation/Service

(1) Rubbed at frame at the hallway closet, we recommend correction by a qualified professional.



11.4 Item 1(Picture) Hallway.

456 Main St. Page 81 of 200



11.4 Item 2(Picture) Hallway.

456 Main St. Page 82 of 200

(2) Did not latch properly at the master bathroom toilet, we recommend correction.



11.4 Item 3(Picture) Master bathroom.

456 Main St. Page 83 of 200




11.4 Item 4(Picture) Master bathroom.

11.5 Windows (Representative number)

Comments: Repair or Replace

456 Main St. Page 84 of 200

(1) Fogged windows indicate a failure of the energy efficiency of the window system; we recommend replacement. We identify all fogged windows that are readily visible during our inspection; however due to owner property and lighting conditions we may not be able to identify all defective conditions. Several window makers have extended warranties on failed window sills; we recommend further inquiry.



11.5 Item 1(Picture) Formal living room.

456 Main St. Page 85 of 200



11.5 Item 2(Picture) Formal living room.

456 Main St. Page 86 of 200



11.5 Item 3(Picture) Formal living room.

456 Main St. Page 87 of 200



11.5 Item 4(Picture) Formal living room.

456 Main St. Page 88 of 200

(2) Moisture staining observed at the formal living room window sill; this indicates a possible defective sill; we recommend further evaluation and corrections by a licensed window contractor.



11.5 Item 5(Picture) Formal living room.

456 Main St. Page 89 of 200



11.5 Item 6(Picture) Formal living room.

456 Main St. Page 90 of 200

(3) Broken sash is a defect when a window will not remain in the open position, and can result in the window free falling to the sill; we recommend correction for safety.



11.5 Item 7(Picture) Formal living room.

456 Main St. Page 91 of 200



11.5 Item 8(Picture) Formal living room.

456 Main St. Page 92 of 200

(4) Caulking deterioration observed at the dining room window; we recommend servicing.



11.5 Item 9(Picture) Dining room.

456 Main St. Page 93 of 200



11.5 Item 10(Picture) Dining room.

456 Main St. Page 94 of 200

(5) Moisture intrusion at sills at the family room and master bedroom, this is an indication of leakage, we recommend leak testing of the windows and repairs as needed by a licensed window contractor.




11.5 Item 11(Picture) Family room.

456 Main St. Page 95 of 200




11.5 Item 12(Picture) Family room.

456 Main St. Page 96 of 200



11.5 Item 13(Picture) Family room.

456 Main St. Page 97 of 200



11.5 Item 14(Picture) Family room.

456 Main St. Page 98 of 200



11.5 Item 15(Picture) Family room.

456 Main St. Page 99 of 200



11.5 Item 16(Picture) Master bedroom.



11.5 Item 17(Picture) Master bedroom.

456 Main St. Page 100 of 200




11.5 Item 18(Picture) Master bedroom.



11.5 Item 19(Picture) Master bedroom.

456 Main St. Page 101 of 200



11.5 Item 20(Picture) Master bedroom.

456 Main St. Page 102 of 200



11.5 Item 21(Picture) Master bedroom.



11.5 Item 22(Picture) Master bedroom.

(6) Older double pane windows can fog and loose their energy efficiency. We do our best to identify these windows during our inspection. However, due to lighting conditions, we may not be able to identify all defects.

11.6 Exterior Doors

Comments: Inspected

11.7 Sliders

Comments: Inspected

456 Main St. Page 103 of 200

11.8 Closet Doors

Comments: Inspected

11.9 Closets

Comments: Inspected

11.10 Screens

Comments: Inspected

11.11 Comments

Comments: Inspected

(1) Owner property, air fresheners, recent repairs, open windows or recent paint will *limit our physical inspection of*

the property.

Child Safety: If young children will be present in the home, we recommend visiting www.charlieshouse.org/safety/ for their in home safety checklist; for example it includes: Secure tip prone furniture to walls; Install safety gates at top and bottom of stairs; Use plug covers over electrical outlets; Lock cabinets that children should not get into; Use doorknob covers; Test smoke and carbon monoxide alarms every 6 months; Keep water heater below 120 degrees; Keep cribs away from windows; Install window coverings without cords; Keep a fire extinguisher in the kitchen; Apply stove covers and use back burners first; Place knives and matches out of children's reach, Lock firearms, etc.

(2) Our primary focus is to identify defects that may present a safety hazard. **Un-permitted property modifications** may be present, with defects that are not readily visible. These types of un-permitted modifications are often associated with poor quality workmanship and hidden safety hazards. We recommend that you contact the local building authority to determine if modifications, upgrades and add-ons have final permit documentation.

The interior of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. The inspection did not involve moving furniture and inspecting behind furniture, area rugs or areas obstructed from view. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

456 Main St. Page 104 of 200

12. Bathroom and Components

Steamers, saunas, whirlpools, bidets, shower pans, dye testing toilets for leaks and overflow fixtures are beyond the scope of this inspection. Pre 1994 faucets and toilets should be upgraded for water use savings. Readily visible electrical, enclosure, cabinets, fixtures and plumbing are inspected using normal operating controls. Whirlpool tub components are inspected if readily accessible. Whirlpool equipment functionality is beyond the scope of this inspection.

Styles & Materials

Exhaust Fans:

Fan

Items

12.0 Counters and Cabinets

Comments: Inspected

12.1 Windows

Comments: Evaluation/Service

Possible termites observed at the master bathroom window sill; we recommend further evaluation by a termite professional.



12.1 Item 1(Picture) Master bathroom.

12.2 Plumbing Drain, Waste and Vent Systems (Sink)

Comments: Inspected

12.3 Plumbing Water Supply and Distribution Systems and Fixtures (Sink)

Comments: Inspected

Effective 2017, homes built before 1994 require water conserving plumbing faucets exceeding: 2.2 gallons per minute. REFER TO YOUR TRANSFER DISCLOSURE STATEMENT.

12.4 Outlets Switches and Fixtures

Comments: Inspected

12.5 Exhaust fan

Comments: Inspected

456 Main St. Page 105 of 200

12.6 Toilet

Comments: Evaluation/Service

(1) The current toilet flush standard is 1.29 gallons (ultra low flow) for new construction effective. Many cities are requiring conversion of toilets to this standard at the time of a real estate sale. We recommend upgrading whether or not is required; to a dual flush model that uses only 1.1 gallons per flush. Effective 2017, homes built before 1994 require water conserving plumbing fixtures exceeding: for toilets 1.6 gallons, urinals 1.0 gallon.. REFER TO YOUR TRANSFER DISCLOSURE STATEMENT.

(2) Lacks caulking: at the master bathroom; we recommend servicing.



12.6 Item 1(Picture) Master bathroom.

12.7 Shower/Bath Plumbing

Comments: Inspected

Effective 2017, homes built before 1994 require water conserving plumbing fixtures exceeding: for showerhead 2.5 gallons per minute, and interior faucets 2.2 gallons per minute. REFER TO YOUR TRANSFER DISCLOSURE STATEMENT.

456 Main St. Page 106 of 200

12.8 Bath/Shower/ Enclosure


Comments: Evaluation/Service

Caulking deterioration observed at the upper hallway bathroom shower enclosure; this condition can result in water seeping between the shower surface and liner and can result in mold growth; we recommend re-caulking.



12.8 Item 1(Picture) Upper hallway bathroom.

456 Main St. Page 107 of 200



12.8 Item 2(Picture) Upper hallway bathroom.

456 Main St. Page 108 of 200



12.8 Item 3(Picture) Upper hallway bathroom.

456 Main St. Page 109 of 200



12.8 Item 4(Picture) Upper hallway bathroom.

12.9 Shower Door

Comments: Inspected

12.10 Floor

Comments: Inspected

12.11 Walls

Comments: Evaluation/Service

456 Main St. Page 110 of 200

There were moisture stains observed at the upper hallway bathroom wall behind the vanity; this can be due to a historic moisture event; we recommend further evaluation by a plumber to verify that the moisture source has been corrected.



12.11 Item 1(Picture) Upper hallway bathroom.

12.12 Ceiling

Comments: Evaluation/Service

456 Main St. Page 111 of 200

Signs of repairs noticed at the lower hallway bathroom ceiling; we recommend further inquiry of the seller.



12.12 Item 1(Picture) Lower hallway bathroom.

12.13 Access Cover

Comments: Not Present

456 Main St. Page 112 of 200

13. Indoor Air Quality

Indoor air quality problems may not be readily visible. A limit mold inspection was included with this home inspection. Mold samples may need to be collected to better determine exposure potentials; this testing was recommended even if suspect conditions were not readily visible. RADON GAS is the number 1 cause of mortality in homes. The EPA therefore recommends that ALL homes be tested for radon levels.

Items

13.0 Mold

Comments: Inspected

The home inspection included a physical investigation for readily visible mold. Even if visible mold conditions were not identified in our inspection report, we recommend that you retain us to conduct mold sampling to help determine if atypical mold conditions are present that were not readily visible. There are additional fees for collecting and submitting mold samples to an AIHA certified laboratory for analysis. If you do not approve mold testing this is contrary to our advice.

456 Main St. Page 113 of 200

14. Energy Conservation

An energy conservation inspection was completed as part of this home inspection. You can save up to \$400 in energy costs per year if you implement our recommendations. Utility, local. state and federal energy rebates are still available. Faucets and toilets installed before 1994 are now required to be upgraded to current water saving standards if permitted work is completed.

An energy conservation inspection was completed as part of this home inspection. You can save up to \$400 in energy costs per year if you implement our recommendations. Utility, local. state and federal energy rebates are still available. Faucets and toilets installed before 1994 are now required to be upgraded to current water saving standards if permitted work is completed.

Items

14.0 Lighting

Comments: Inspected

LIGHTING USE IS TYPICALLY 5% OF YOUR ENERGY USAGE. Replace incandescent lights with LED. These bulbs use up ot 80% less energy. Look for sales and rebates e.g. CostCo. LED bulbs claim a lifetime of 23 years, they take no time to warm up, are not effected by frequent on/off, are dimmable, contain no mercury, have very good color rendering and have a payback time of 1 year. They can also be used outdoors, but need to be protected from water.

When shopping for an LED, take your old bulb with you to make sure the new one will fit your fixture. If the bulb is for an enclosed fixture, be sure the LED is rated for such.

Do not use LED and CFL in the same fixture or a dimmer, which can cause disruptions in performance.

LED prices have dropped 83% over the past 4 years.

Dimmers can reduce electrical use at lower light settings. If using with LED's be sure the bulbs are rated for such use.

Motion detector switches are useful for rooms where occupants have a habit of forgetting to turn the lights off when they leave: e.g. laundry, closets, etc.

14.1 HEATING AND AC

Comments: Inspected

(1) HEATING CAN ACCOUNT FOR 43% OF YOUR ENERGY BILL. Get an advanced HVAC cleaning and tune up. This will include sealing duct leaks which can save an additional 25 to 45% of conditioned air energy cost (hot and cold) to be lost to leakage.

HOWEVER, DO NOT HAVE YOUR DUCTS CLEANED; SEE MY WEBSITE VIDEOS TO LEARN ALL ABOUT THIS UNNEEDED SERVICE, THAT DOES NOT IMPROVE INDOOR AIR QUALITY.

Replace your aging HEATING system with an energy star model for an average \$400 per year savings.

Contact your utility to see if they have an AC summer saver program. If so, you can save up to \$200 a year in rebates.

Replace often used central air conditioner systems that are more than 10 years old, for a newer model that will be up to 40% more efficient.

Install and use ceiling fans to reduce the need for AC utilization,

Install a programmable thermostat, which can automatically adjust the temperature in your home for maximum savings and comfort.

Do not replace windows just to save energy, unless your windows are failing. For windows being replaced with frequent direct sunlight, choose new ones with a low-E coating that reflects heat. Consider MILGARD brand windows due to their extended warranty. Dual pain windows that fog between their panes have lost their energy efficiency and need replacement.

456 Main St. Page 114 of 200

Burning in a wood-burning fireplace is an inefficient way of heating a home, since most heat goes out the chimney. They also pollute 20 times the amount of an EPA certified stove.

If you use a fireplace for heat, expect other rooms in the home to be cooler due to escaping warm air.

For more efficient heating with less interior and exterior pollution, arrange for installation of a gas, pellet or EPA certified wood fireplace insert, by a NFI certified professional.

Installing glass doors over a current fireplace can help reduce some energy loss, however, the doors must be matched properly by a NFI certified professional.

(2) COOLING CAN BE 7% OF YOUR ENERGY BILL.

14.2 ATTIC AND CRAWLSPACE

Comments: Inspected

Upgrade insulation to current standards of 11 inches of fiberglass or rock wool or 8 inches of cellulose.

Seal attic leaks: inner and outer walls at the attic floor, dropped ceiling areas, stud cavities, flues, vents. electrical boxes, and attic hatch.

14.3 Windows

Comments: Inspected

Upgrade to dual pane window system if you need to replace your windows. Newer dual pane windows will improve energy efficiency, reduce drafts and noise, as well as provide ultra violet protection.

Weather strip and caulk.

14.4 Doors

Comments: Inspected Weather strip and caulk.

14.5 Water Heater

Comments: Inspected

WATER HEATERS USE UP TO 16% OF ENERGY USAGE. A solar water heater with tax incentives can pay for itself in 3 to 5 years.

Water heaters 10 years or older should be considered for and Energy Star unit upgrade. Tankless or high energy efficiency tank water heaters can provide a 30% energy savings. Rebates may be available from local retailers and utilities.

Wash your clothes in cold water. Consumer reports has identified top rated detergents that deliver superb cold water cleaning.

Install low-flow faucets and showerheads, these will save water heating energy as well as saving water usage.

14.6 CLOTHES WASHER AND DRYER

Comments: Not Inspected

14.7 Refrigerator

Comments: Not Inspected

APPLIANCES ARE 9% OF ENERGY COSTS.

14.8 Dishwasher

Comments: Inspected

Run the dishwasher only when it is full, and use the rinse feature sparingly, since it uses 3 to 7 gallons of water. Upgrade to an energy star model for water and electric savings.

456 Main St. Page 115 of 200

14.9 Stove

Comments: Inspected

Upgrade to an energy star model for savings.

14.10 Water

Comments: Inspected

(1) The current toilet flush standard is 1.29 gallons (ultra low flow) for new construction effective 1/1/14. Many cities are requiring conversion of toilets to this standard at the time of a real estate sale. We recommend upgrading whether or not is required; to a dual flush model that uses only 1.1 gallons per flush.

Install low flow showerheads, and sink aerators.

Use drought resistant native plants, mulch and drip systems.

(2) Effective 2017, homes built before 1994 require water conserving plumbing fixtures exceeding: for toilets 1.6 gallons, urinals 1.0 gallon. showerhead 2.5 gallons per minute, and interior faucets 2.2 gallons per minute. REFER TO YOUR TRANSFER DISCLOSURE STATEMENT. The current toilet flush standard is 1.29 gallons. (ultra low flow). Some cities are requiring conversion of toilets at the time of sale. Dual flush toilets that are now available have flush at 1.1 gallons. We recommend upgrading to these new standards whether required or not to conserve water usage.

Install low flow showerheads, and sink aerators.

Use drought resistant native plants, mulch and drip systems.

14.11 Solar

Comments: Not Inspected

After the above conservation efforts, your electric bill is over \$125 per month, it is cost effective to consider electric solar panels.

Go to www.gosolarcalifornia.org to see what rebates you qualify for; there is also a 30% federal tax credit until 2017; if you purchase the system, rather than leasing. California solar rebate funds have been exhausted and the program is closed.

According to the Solar Energy Industries Assoc. the typical installation costs about \$15,000 to \$21,000. Solar panels are usually warranted for 20-25 years, and pay for themselves in 5 to 10 years. However you may find further savings through COST-CO vendors.

For a list of certified installers visit: nabcep.org or seia.org. Find out if the installer you pick will apply for all the required permits, uses subcontractors and is properly licensed.

14.12 ELECTRONICS

Comments: Inspected

ELECTRONICS USE UP TO 4% OF ENERGY COSTS. Ask your cable company to upgrade the set top box to the latest 4.1 Energy Star device for a 35% energy savings.

Unplug computers, stereos, and video games that draw energy when they are off.

Decade old flat screens cost \$65 a year to run; by replacing it with a newer model will cost \$25 in electricity.

456 Main St. Page 116 of 200

General Summary



Guaranteed Property and Mold Inspections.

2372 Morse Ave. Suite 257 Irvine, CA 92614 949.230.6800

CustomerSample Report

Address 456 Main St. Irvine CA

The following items or discoveries indicate that these systems or components **do not function as intended** or **adversely affects the habitability of the dwelling**; or **warrants further investigation by a specialist**, or **requires subsequent observation**. This summary shall not contain recommendations for routine upkeep of a system or component to keep it in proper functioning condition or recommendations to upgrade or enhance the function or efficiency of the home. This Summary is not the entire report. The complete report may include additional information of concern to the customer. It is recommended that the customer read the complete report.


2. Exterior

2.0 Wall Cladding, Flashing and Trim

Evaluation/Service


(1) Signs of stucco repairs observed at the left side of the structure; we recommend further inquiry of the seller.

456 Main St. Page 117 of 200



2.0 Item 1(Picture) Left side of the structure.

456 Main St. Page 118 of 200



2.0 Item 2(Picture) Left side of the structure.

(2) Poor weep screed clearance (2" above paving; 4" above soil); this condition results in corrosion, and unwanted moisture intrusion into the wall and interior that may not be readily visible.

456 Main St. Page 119 of 200



2.0 Item 3(Picture) Left side of the structure (planter)

(3) Stucco is susceptible to cracking. Cracks to not imply that the function has been degraded. Only cracks larger than 3/32" and excessive indicate a problem. We recommend however, that all cracks by sealed by a stucco professional.

2.1 Doors (Exterior)

Repair or Replace


The front door handle appears to have been replaced; cracks exist around the handle; we recommend repairs.

456 Main St. Page 120 of 200



2.1 Item 1(Picture) Front door.

456 Main St. Page 121 of 200



2.1 Item 2(Picture) Front door.

456 Main St. Page 122 of 200



2.1 Item 3(Picture) Front door.

2.2 Windows

Evaluation/Service


(1) The wood trim at the exterior window front of the structure are moisture damaged; we recommend further evaluation and repairs by a termite professional.

456 Main St. Page 123 of 200



2.2 Item 1(Picture) Front of the structure.

456 Main St. Page 124 of 200



2.2 Item 2(Picture) Front of the structure.



2.2 Item 3(Picture) Front of the structure.

(2) Caulking deterioration at the front of the structure, we recommend servicing.

456 Main St. Page 125 of 200



2.2 Item 4(Picture) Front of the structure.

456 Main St. Page 126 of 200



2.2 Item 5(Picture) Front of the structure.

2.4 Eaves, Soffits, Fascias, Beam Ends and Rafters

Evaluation/Service

Moisture damage; we recommend further evaluation by a termite professional, to determine the extent of moisture damage to the wood structure.

456 Main St. Page 127 of 200



2.4 Item 1(Picture) Front of the structure.

456 Main St. Page 128 of 200



2.4 Item 2(Picture) Front of the structure.



2.4 Item 3(Picture) Right side of the structure.

456 Main St. Page 129 of 200



2.4 Item 4(Picture) Right side of the structure.

2.12 Sprinklers

Evaluation/Service

Sprinkler system leaking at the right side of the structure; we recommend corrections by a plumber.

456 Main St. Page 130 of 200



2.12 Item 1(Picture) Right side of the structure.

2.15 Trees and Plants

Evaluation/Service

(1) Neighbor tree over roof area, we recommend trimming to protect the roof coverings.

456 Main St. Page 131 of 200



2.15 Item 1(Picture) Roof.

(2) Touching the structure, we recommend trimming.

456 Main St. Page 132 of 200



2.15 Item 2(Picture) Right side of the structure.

3. Electrical System

3.6 Branch Circuit Conductors, Overcurrent Devices and Compatability of their Amperage and Voltage Evaluation/Service


Loose breakers we recommend evaluation by a licensed electrician for enhanced safety.

456 Main St. Page 133 of 200




3.6 Item 1(Picture) Service panel.

456 Main St. Page 134 of 200



3.6 Item 2(Picture) Service panel.



3.6 Item 3(Picture) Service panel.

3.9 Grounding (and or GFCI) of Receptacles within 6 feet of interior plumbing fixtures, and all receptacles in garage, carport and exterior walls

Repair or Replace

We recommend that all outlets within 6' of wet areas be upgraded to GFCI for enhanced safety.

456 Main St. Page 135 of 200



3.9 Item 1(Picture) Kitchen island.

456 Main St. Page 136 of 200



3.9 Item 2(Picture) Kitchen island.

456 Main St. Page 137 of 200



3.9 Item 3(Picture) Kitchen island.

456 Main St. Page 138 of 200




3.9 Item 4(Picture) Laundry room.

456 Main St. Page 139 of 200



3.9 Item 5(Picture) Laundry room.

456 Main St. Page 140 of 200



3.9 Item 6(Picture) Lower hallway bathroom.

456 Main St. Page 141 of 200



3.9 Item 7(Picture) Master bathroom.

456 Main St. Page 142 of 200



3.9 Item 8(Picture) Master bathroom.

456 Main St. Page 143 of 200



3.9 Item 9(Picture) Master bathroom.

4. Roofing / Chimneys / Roof Structure and Attic

4.4 Roof Drainage Systems (gutters and downspouts)

Evaluation/Service

The downspout at the front of the structure is not mounted to the wall; we recommend repairs.

456 Main St. Page 144 of 200



4.4 Item 1(Picture) Front of the structure.

456 Main St. Page 145 of 200



4.4 Item 2(Picture) Front of the structure.

4.10 Visible Electric Wiring in Attic

Evaluation/Service

Exposed splices, we recommend a complete evaluation of the electrical system in the attic since this is an indication that work was not completed by a licensed electrician; this is a safety hazard.

456 Main St. Page 146 of 200



4.10 Item 1(Picture) Attic.

5. Plumbing System

5.6 Main Fuel Shut-off

Repair or Replace

Gas meter lacks seismic shut off device, we recommend installation for enhanced safety.



5.6 Item 1(Picture) Gas meter.

456 Main St. Page 147 of 200

6. Garage

6.5 Garage Door Controls and Auto Reverse

Repair or Replace

Optical sensors are more than 6" above the ground, recommend corrections for child and pet safety.




6.5 Item 1(Picture) Garage.

6.6 Occupant Door from Garage to inside home

Repair or Replace

The occupant door from inside garage to inside the home is not a fire rated door. This means that should a fire occur in garage, the occupant door does not afford protection until fireman arrive. This door should be replaced with a fire rated door.

456 Main St. Page 148 of 200



6.6 Item 1(Picture) Garage door.

8. Water Heater

8.2 Plumbing Connections

Repair or Replace

Hot and cold water lines are missing R-4 insulation, we recommend installation for energy savings.

456 Main St. Page 149 of 200



8.2 Item 1(Picture) Water heater.

8.6 Seismic Strapping

Repair or Replace

52+ size water heater requires a third seismic strap at mid-line, we recommend installation to meet CA seismic guidelines.



8.6 Item 1(Picture) Water heater.

8.7 Firewall/Platform

456 Main St. Page 150 of 200

Evaluation/Service

The water heater appears to be slightly leaning; we recommend further evaluation by a licensed plumber.



8.7 Item 1(Picture) Water heater.


9. Kitchen Components and Appliances

9.12 Air Gap

Repair or Replace

Not installed, this can result in waste water mixing into the clean cycle; note that a few models have an internal air gap (which is not common); recommend installation for water quality safety.

456 Main St. Page 151 of 200



9.12 Item 1(Picture) Air gap.

9.14 Range Hood

Repair or Replace

(1) Disconnected at the exhaust, we recommend correction by securing with 3 metal sheet screws at each end and sealing with aluminum tape.



9.14 Item 1(Picture) Range exhaust.

456 Main St. Page 152 of 200



9.14 Item 2(Picture) Range exhaust.

(2) The left side heating bulb did not respond to test; we recommend replacement.



9.14 Item 3(Picture) Range hood.

10. Heating / Central Air Conditioning

10.6 Enclosure

Evaluation/Service

456 Main St. Page 153 of 200

Possible rodent droppings observed at the HVAC enclosure; we recommend further evaluation and cleanup by a integrated pest control specialist.



10.6 Item 1(Picture) HVAC enclosure.

456 Main St. Page 154 of 200



10.6 Item 2(Picture) HVAC enclosure.

10.8 Distribution Systems (including visible fans, pumps, ducts and piping).

Evaluation/Service

Aging ducts, we recommend leak testing, and budgeting for replacement. NOTE THAT DUCTS SHOULD NOT BE CLEANED.

456 Main St. Page 155 of 200




10.8 Item 1(Picture) HVAC ducting.

456 Main St. Page 156 of 200



10.8 Item 2(Picture) HVAC ducting.

456 Main St. Page 157 of 200



10.8 Item 3(Picture) HVAC ducting.

10.9 Air Return Chamber

Repair or Replace

Lacks drywall enclosure, recommend installation to eliminate using air from inner walls of the structure.

456 Main St. Page 158 of 200



10.9 Item 1(Picture) Air return chamber.



10.9 Item 2(Picture) Air return chamber.

10.10 HVAC Filter

Repair or Replace

(1) Missing at the air return; we recommend replacement with an allergy rated disposable filter.

456 Main St. Page 159 of 200



10.10 Item 1(Picture) Lower hallway.

(2) Poorly sized at the master bedroom, we recommend replacement with an allergy rated disposable filter.



10.10 Item 2(Picture) Master bedroom.

10.13 AC Condensation Lines

Evaluation/Service

- (1) Not fully visible, leak testing is beyond the scope.
- (2) The condensation drip line that terminates to the exterior appears to impact the side wall when draining; we recommend extending the drip line to ensure moisture does not come into contact with the cladding wall.

456 Main St. Page 160 of 200



10.13 Item 1(Picture) Rear of the structure.

(3) A secondary drain line or auto disconnect device was not installed; these should be installed if blockage in the primary line could cause damage to the structure.



10.13 Item 2(Picture) HVAC.

11. Interior

11.0 Ceilings

456 Main St. Page 161 of 200

Evaluation/Service

Signs of repairs noticed at the formal living room ceiling and kitchen ceiling; we recommend further inquiry of the seller.



11.0 Item 1(Picture) Formal living room.

456 Main St. Page 162 of 200



11.0 Item 2(Picture) Formal living room.



11.0 Item 3(Picture) Formal living room.

456 Main St. Page 163 of 200



11.0 Item 4(Picture) Kitchen ceiling.

11.1 Walls

Evaluation/Service

(1) Signs of warping at the master bedroom wall beneath the windows; this can be due to moisture intrusion from the exterior; we recommend further evaluation by a licensed contractor.

456 Main St. Page 164 of 200



11.1 Item 1(Picture) Master bedroom.

456 Main St. Page 165 of 200



11.1 Item 2(Picture) Master bedroom.

(2) There was damaged observed at the master bedroom closet lower wall; we recommend repairs.

456 Main St. Page 166 of 200



11.1 Item 3(Picture) Master bedroom.

11.2 Floors

Evaluation/Service

(1) Floor noise at upper level master bedroom closet, this is not atypical for older homes, however it can be an indication of poor installation practices and defects, we recommend further evaluation. These conditions can often be improved by the application of additional screws in the floor boards at the joists.



11.2 Item 1(Picture) Master bedroom closet.

(2) Lifted flooring observed at the upper hallway; we recommend corrections by a licensed contractor.

456 Main St. Page 167 of 200



11.2 Item 2(Picture) Upper hallway flooring.




11.2 Item 3(Picture) Upper hallway flooring.

11.4 Doors (Representative number)

Evaluation/Service


(1) Rubbed at frame at the hallway closet, we recommend correction by a qualified professional.

456 Main St. Page 168 of 200



11.4 Item 1(Picture) Hallway.

456 Main St. Page 169 of 200



11.4 Item 2(Picture) Hallway.

(2) Did not latch properly at the master bathroom toilet, we recommend correction.

456 Main St. Page 170 of 200



11.4 Item 3(Picture) Master bathroom.

456 Main St. Page 171 of 200




11.4 Item 4(Picture) Master bathroom.

11.5 Windows (Representative number)

Repair or Replace


(1) Fogged windows indicate a failure of the energy efficiency of the window system; we recommend replacement. We identify all fogged windows that are readily visible during our inspection; however due to owner property and lighting conditions we may not be able to identify all defective conditions. Several window makers have extended warranties on failed window sills; we recommend further inquiry.

456 Main St. Page 172 of 200



11.5 Item 1(Picture) Formal living room.

456 Main St. Page 173 of 200



11.5 Item 2(Picture) Formal living room.

456 Main St. Page 174 of 200



11.5 Item 3(Picture) Formal living room.

456 Main St. Page 175 of 200



11.5 Item 4(Picture) Formal living room.

(2) Moisture staining observed at the formal living room window sill; this indicates a possible defective sill; we recommend further evaluation and corrections by a licensed window contractor.

456 Main St. Page 176 of 200



11.5 Item 5(Picture) Formal living room.

456 Main St. Page 177 of 200



11.5 Item 6(Picture) Formal living room.

(3) Broken sash is a defect when a window will not remain in the open position, and can result in the window free falling to the sill; we recommend correction for safety.

456 Main St. Page 178 of 200



11.5 Item 7(Picture) Formal living room.


456 Main St. Page 179 of 200



11.5 Item 8(Picture) Formal living room.

(4) Caulking deterioration observed at the dining room window; we recommend servicing.

456 Main St. Page 180 of 200



11.5 Item 9(Picture) Dining room.

456 Main St. Page 181 of 200



11.5 Item 10(Picture) Dining room.

(5) Moisture intrusion at sills at the family room and master bedroom, this is an indication of leakage, we recommend leak testing of the windows and repairs as needed by a licensed window contractor.

456 Main St. Page 182 of 200




11.5 Item 11(Picture) Family room.

456 Main St. Page 183 of 200




11.5 Item 12(Picture) Family room.

456 Main St. Page 184 of 200



11.5 Item 13(Picture) Family room.

456 Main St. Page 185 of 200



11.5 Item 14(Picture) Family room.

456 Main St. Page 186 of 200




11.5 Item 15(Picture) Family room.

456 Main St. Page 187 of 200



11.5 Item 16(Picture) Master bedroom.



11.5 Item 17(Picture) Master bedroom.

456 Main St. Page 188 of 200



11.5 Item 18(Picture) Master bedroom.



11.5 Item 19(Picture) Master bedroom.

456 Main St. Page 189 of 200



11.5 Item 20(Picture) Master bedroom.

456 Main St. Page 190 of 200



11.5 Item 21(Picture) Master bedroom.



11.5 Item 22(Picture) Master bedroom.

(6) Older double pane windows can fog and loose their energy efficiency. We do our best to identify these windows during our inspection. However, due to lighting conditions, we may not be able to identify all defects.

12. Bathroom and Components

12.1 Windows

456 Main St. Page 191 of 200

Evaluation/Service

Possible termites observed at the master bathroom window sill; we recommend further evaluation by a termite professional.



12.1 Item 1(Picture) Master bathroom.

12.6 Toilet

Evaluation/Service

(1) The current toilet flush standard is 1.29 gallons (ultra low flow) for new construction effective. Many cities are requiring conversion of toilets to this standard at the time of a real estate sale. We recommend upgrading whether or not is required; to a dual flush model that uses only 1.1 gallons per flush. Effective 2017, homes built before 1994 require water conserving plumbing fixtures exceeding: for toilets 1.6 gallons, urinals 1.0 gallon.. REFER TO YOUR TRANSFER DISCLOSURE STATEMENT.

(2) Lacks caulking: at the master bathroom; we recommend servicing.

456 Main St. Page 192 of 200



12.6 Item 1(Picture) Master bathroom.

12.8 Bath/Shower/ Enclosure

Evaluation/Service


Caulking deterioration observed at the upper hallway bathroom shower enclosure; this condition can result in water seeping between the shower surface and liner and can result in mold growth; we recommend re-caulking.

456 Main St. Page 193 of 200



12.8 Item 1(Picture) Upper hallway bathroom.

456 Main St. Page 194 of 200



12.8 Item 2(Picture) Upper hallway bathroom.

456 Main St. Page 195 of 200



12.8 Item 3(Picture) Upper hallway bathroom.

456 Main St. Page 196 of 200



12.8 Item 4(Picture) Upper hallway bathroom.

12.11 Walls

Evaluation/Service

There were moisture stains observed at the upper hallway bathroom wall behind the vanity; this can be due to a historic moisture event; we recommend further evaluation by a plumber to verify that the moisture source has been corrected.




12.11 Item 1(Picture) Upper hallway bathroom.

456 Main St. Page 197 of 200

12.12 Ceiling

Evaluation/Service

Signs of repairs noticed at the lower hallway bathroom ceiling; we recommend further inquiry of the seller.



12.12 Item 1(Picture) Lower hallway bathroom.

12.13 Access Cover

Not Present

Home inspectors are not required to report on the following: Life expectancy of any component or system; The causes of the need for a repair; The methods, materials, and costs of corrections; The suitability of the property for any specialized use; Compliance or non-compliance with codes, ordinances, statutes, regulatory requirements or restrictions; The market value of the property or its marketability; The advisability or inadvisability of purchase of the property; Any component or system that was not observed; The presence or absence of pests such as wood damaging organisms, rodents, or insects; or Cosmetic items, underground items, or items not permanently installed. Home inspectors are not required to: Offer warranties or

456 Main St. Page 198 of 200

guarantees of any kind; Calculate the strength, adequacy, or efficiency of any system or component; Enter any area or perform any procedure that may damage the property or its components or be dangerous to the home inspector or other persons; Operate any system or component that is shut down or otherwise inoperable; Operate any system or component that does not respond to normal operating controls; Disturb insulation, move personal items, panels, furniture, equipment, plant life, soil, snow, ice, or debris that obstructs access or visibility; Determine the presence or absence of any suspected adverse environmental condition or hazardous substance, including but not limited to mold, toxins, carcinogens, noise, contaminants in the building or in soil, water, and air; Determine the effectiveness of any system installed to control or remove suspected hazardous substances; Predict future condition, including but not limited to failure of components; Since this report is provided for the specific benefit of the customer(s), secondary readers of this information should hire a licensed inspector to perform an inspection to meet their specific needs and to obtain current information concerning this property.

Prepared Using HomeGauge http://www.HomeGauge.com : Licensed To Joseph Gutierrez

456 Main St. Page 199 of 200



Guaranteed Property and Mold Inspections.

2372 Morse Ave. Suite 257 Irvine, CA 92614 949.230.6800

Report Attachments

ATTENTION: This inspection report is incomplete without reading the information included herein at these links/attachments. Note If you received a printed version of this page and did not receive a copy of the report through the internet please contact your inspector for a printed copy of the attachments.

warranty

456 Main St. Page 200 of 200